

FIG. 1




FIG. 2




FIG. 3




FIG. 4 (B)




FIG. 4 (A)





FIG. 5



01/15/2005

Fig. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10 (A)




FIG. 10 (B)




FIG. 11




FIG. 12






FIG. 13




FIG. 14




FIG. 15




FIG. 16 (A)




FIG. 16 (B)




FIG. 17




FIG. 18




FIG. 19





FIG. 20



387521179

FIG. 21 (A)




FIG. 21 (B)

VIEW ALONG ARROW A





FIG. 21 (C)



ENLARGED VIEW OF BLADE EDGE

FIG. 22




FIG. 23




FIG. 24

